



Ax5




Bx1



Ax1



Dx1



Ex4



M6x20

Fx8



M6x25

Gx2




Hx1



Ix1



Jx8



Kx1




GC-6048


ZOLDER

ASSEMBLE INSTRUCTIONS


Step1




Step2




Step3



Step4



Step5



Step6

